




EIBENSTOCK
Elektrowerkzeuge

Ersatzteilliste

MXT 100/2



MXT 100/2 - 230 V

EIBENSTOCK

071I2000

No.	Description	Order No.	Pcs
1	motor housing	671I1001	1
2	brush holder	80201196	2
3	lock washer B4	80201385	4
4	self tapping screw CM4x12	80201180	4
5			
6			
7			
8	cap	671I1008	1
9	self tapping screw HC4,2x60	80201519	4
10	stator complete	671I2010	1
11	self tapping screw HC 3,9x60	80201266	2
12	bearing cap	671I1012	1
13	grooved ball bearing 608 2Z	80410011	1
14a	rotor complete 8 Z.	671I2014	1
14b	rotor complete 6 Z.	671I2015	1
15	grooved ball bearing 6001 2RS	80410032	1
16	strain relief	671I1016	1
17	self tapping screw HC 4,2x16	80201271	2
18	air guiding ring	671I1018	1
19	self tapping screw black HC4,2x22	80201478	10
20	cable grommet	771C6255	1
21	gearbox housing	671I2021	1
22			
23			
24			

No.	Description	Order No.	Pcs
25			
26			
27			
28			
29			
30			
31			
32a	pinion shaft 44/17/11 Z.	671I2032	1
32b	pinion shaft 33/17/11 Z.	671I2033	1
33			
34			
35	needle sleeve HK 0810	80420110	2
36	shaft	671I2036	1
37	fitting key A5x5x28	80200602	1
38	gear block	671I2038	1
39	end shield of gearing	671I1035	1
40	notched pin plug 4x12	80200582	1
41	gearbox seal	671I2041	1
42	screw 4,8x55	671I1033	4
43	coupling bolt complete	671I2043	1
44	gear switch complete	671I2044	1
45	carbon brush 6,3x10x18	80700013	2
46	switch	671I1037	1
47	anti parasite condenser	6660W014	1
48	connecting cable	80600060	1